

Honeywell International Inc.
12001 Hwy 55
Plymouth, MN 55441-4744
763-954-2474

March 14, 2008

Subject: End-of-Life Buy of Honeywell's HMC1052 MSSOP

Honeywell is announcing the discontinuance of part number HMC1052 MSSOP, 2 axis magnetic sensor in a 10 pin SOIC package. (Honeywell internal part, 22024168-027 (tape & reel), 22024168-024 (cut tape)). The part is being discontinued because our assembly supplier will build this part for us only one more time, due to the difficulty getting raw materials and the low usage of this 10 pin lead frame across the industry. The HMC1052 MSSOP product was introduced to the market 8 years ago.

We are offering an opportunity for an end-of-life lifetime buy as follows:

- The last date to place final orders for the HMC1052 MSSOP part is August 15, 2008.
- The last date for final shipments of the HMC1052 MSSOP part is December 29, 2008.

The replacement for this discontinued part is the HMC1052L in a 16 pin quad flat pack. This part has the same sensing element inside; the only change is the package footprint.

End-of-life orders are non cancellable and the material is not returnable. We encourage you to order as soon as possible. Honeywell's customer service is available at 763-954-2474, fax 763-954-2257.

Sincerely,

Tamara Bratland
Director, Magnetic Sensor Products
Honeywell International
12001 State Hwy 55
Plymouth, MN 55441
763-954-2992
Tamara.bratland@honeywell.com